

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/29/2013  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155667</b>		(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01, 02, 03</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>10/21/2013</b>	
NAME OF PROVIDER OR SUPPLIER  <b>OAK GROVE CHRISTIAN RETIREMENT VILLAGE</b>				STREET ADDRESS, CITY, STATE, ZIP CODE <b>221 W DIVISION ST</b> <b>DEMOTTE, IN 46310</b>			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
{K 000}	<p>INITIAL COMMENTS</p> <p>A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 08/27/13 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 10/21/13</p> <p>Facility Number: 010823 Provider Number: 155667 AIM Number: 200236630</p> <p>Surveyor: Dennis Austill, Life Safety Code Supervisor</p> <p>At this PSR survey, Oak Grove Christian Retirement Village was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire, the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) and 410 IAC 16.2. The original building built prior to March 1, 2003 identified as the Shepard's Care and Skilled unit located on the southeast and southwest wings of the first floor was surveyed with Chapter 19, Existing Health Care Occupancies.</p> <p>The facility is located on the first floor of a two story fully sprinklered building of Type V (111) construction. The facility has a fire alarm system with hardwired smoke detection in the corridors, in resident rooms and in spaces open to the corridors. The facility has the capacity for 59 beds and had a census of 47 at the time of this survey.</p>			{K 000}			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/29/2013  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155667</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01, 02, 03</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>10/21/2013</b>
NAME OF PROVIDER OR SUPPLIER  <b>OAK GROVE CHRISTIAN RETIREMENT VILLAGE</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>221 W DIVISION ST</b> <b>DEMOTTE, IN 46310</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	Continued From page 1  All areas where the residents have customary access and all areas providing facility services were sprinklered.	{K 000}			
{K 000}	Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 10/28/13.  INITIAL COMMENTS  A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 08/27/13 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).  Survey Date: 10/21/13  Facility Number: 010823 Provider Number: 155667 AIM Number: 200236630  Surveyor: Dennis Austill, Life Safety Code Supervisor  At this PSR survey, Oak Grove Christian Retirement Village was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), and 410 IAC 16.2. The Oakleaf unit was surveyed under Chapter 18, New Health Care Occupancies.  The facility is located on the first floor of a two story fully sprinklered building of Type V (111) construction. The facility has a fire alarm system with hardwired smoke detection in the corridors, in resident rooms and in spaces open to the	{K 000}			

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/29/2013  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155667</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01, 02, 03</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>10/21/2013</b>
NAME OF PROVIDER OR SUPPLIER  <b>OAK GROVE CHRISTIAN RETIREMENT VILLAGE</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>221 W DIVISION ST</b> <b>DEMOTTE, IN 46310</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	Continued From page 2 corridors. The facility has the capacity for 59 beds and had a census of 47 at the time of this survey.  All areas where the residents have customary access and all areas providing facility services were sprinklered.	{K 000}			